

## SAFETY RECALL NOTICE FOR SUZUKI OUTBOARD MOTORS

Suzuki Motor Corporation issued a voluntary recall in July 2005 for their Suzuki DF200, DF225, AND DF250 outboard engines.

The recall, as outlined in the service bulletin, indicates Suzuki DF200, DF225, AND DF250 outboard engines within the serial number range. specified below may have a flywheel cast problem that may result in flywheel breakage without warning during engine operation.

If the flywheel breaks, debris from the broken flywheel may break through the flywheel and engine covers, possibly causing severe personal injury.

The engine models and serial numbers included in this recall are:

| ENGINE MODEL | SERIAL NUMBER RANGE          |
|--------------|------------------------------|
| DF200T       | 20001F-421546 THROUGH 421911 |
| DF200Z       | 20001Z-421114 THROUGH 421149 |
| DF225T       | 22501F-421292 THROUGH 421690 |
| DF225Z       | 22501Z-421084 THROUGH 421192 |
| DF250T       | 25001F-422026 THROUGH 422417 |
| DF250Z       | 25001Z-421296 THROUGH 421384 |

If the serial number falls within the range listed, you should contact an authorized suzuki dealer to schedule a recall inspection of the flywheel

Suzuki Marine Web Site with Deal Locator:

<http://www.suzukimarine.com/sr06/df250/>